
Steps to take off personal protective equipment (PPE) including gown

- **3** Remove apron 4 Perform hand **1** Always remove PPE under leaning forward and the guidance and supervision hygiene on gloved taking care to avoid of a trained observer hands. contaminating your (colleague). Ensure that **5** Remove outer pair hands. When infectious waste containers of gloves and removing disposable are available in the doffing dispose of them apron, tear it off area for safe disposal safely. of PPE. Separate containers at the neck and roll it Use the technique should be available for down without shown in Step 17 touching the front reusable items. area. Then untie the 6 Perform hand hygiene on gloved **2** Perform hand hygiene on back and roll the gloved hands.¹ apron forward. hands. 7 Remove head and neck covering taking care to avoid **9** Remove the contaminating your face by starting from the bottom gown by untying of the hood in the back and rolling from back to front
- OR

and from inside to outside, and dispose of it safely.

- 8 Perform hand hygiene on gloved hands.
- **11** Remove eye protection by pulling the string from behind the head and dispose of it safely.



the knot first, then pulling from back to front rolling it from inside to outside and dispose of it safely.



10 Perform hand hygiene on gloved hands.

13 Remove the mask from behind the head by first untying the bottom string above the head and leaving it hanging in front; and then the top string next from behind head and dispose of it safely.




- 14 Perform hand hygiene on gloved hands.
 - **17** Remove gloves carefully with appropriate technique and dispose of them safely.

12 Perform hand hygiene on gloved hands.

15 Remove rubber boots without touching them (or overshoes if wearing shoes). If the same boots are to be used outside of the high-risk zone, keep them on but clean and decontaminate appropriately before leaving the doffing area.²

16 Perform hand hygiene on gloved hands.

by soaking in a 0.5% chlorine solution for 30 min, then rinsed and dried.



18 Perform hand hygiene.

1 While working in the patient care area, outer gloves should be changed between patients and prior to exiting (change after seeing the last patient) 2 Appropriate decontamination of boots includes stepping into a footbath with 0.5% chlorine solution (and removing dirt with toilet brush if heavily soiled with mud and/or organic materials) and then wiping all sides with 0.5% chlorine solution. At least once a day boots should be disinfected



All reasonable precautions have been taken by the World Health Organization to verify the information contained in this publication. However, the published material is being distributed without warranty of any kind, either expressed or implied. The responsibility for the interpretation and use of the material lies with the reader. In no event shall the World Health Organization be liable for damages arising from its use.

我们的产品



大数据平台

国内宏观经济数据库 国际经济合作数据库 行业分析数据库 条约法规平台

国际条约数据库 国外法规数据库

即时信息平台

新闻媒体即时分析 社交媒体即时分析

云报告平台

国内研究报告 国际研究报告

预览已结束,完整报告链接和二维码如下

https://www.yunbaogao.cn/report/index/report?reportId=5_27568